



Figure 5 - Decay to hoodmould



Figure 6 – Decay to stonework to west jamb



Figure 7 – Decay to the east of the arch